

Parker Hannifin Corporation
O-Ring Division
2360 Palumbo Drive
P.O. Box 11751
Lexington, KY 40512 USA
Phone (859) 268 5038

June 30, 2015

Subject: Parker Compound VA151

Dear Valuable Customer,

We are writing to inform you that Parker O-Ring compound VA151-75 due to on going supplier issues will be obsoleted and no longer available effective January 1, 2016. There are multiple compounds offered as replacements for VA151-75 depending on application so please contact O-Ring Applications Engineering for recommended Parker compound.

We recommend a transition from compound immediately VA151-75 to avoid delivery delays.

Parker O-Ring Division regrets the inconvenience this supply issue may cause.

Sincerely,

Millard Abbott
Parker O-Ring Division General Industrial and Distributor Market Manager (859)268-5065
mabbott@parker.com

